



Long Road Racing

2668 Peachtree Road, Statesville, NC 28625

(980) 223-8547 LongRoadRacing.com

Global MX-5 Cup Car Technical Service Bulletin #05-23-2018B

Optional: Global MX-5 Update: Starter power lead

This TSB describes:

1. The main 12V power lead for the starter should be checked for chafing to ground.

Installation:

1. Verify and correct with insulation, and or, re-clocking the starter hot wire (red arrow below) that the starter wire does not contact the chassis bracket (green arrow).



If you have any questions about this Technical Bulletin, please contact Long Road Racing at:

Glenn@LongRoadRacing.com or 980-223-8547