



## Long Road Racing

2668 Peachtree Road, Statesville, NC 28625

(980) 223-8547 LongRoadRacing.com


### Global MX-5 Cup Car Technical Service Bulletin #01-24-2019

Optional: Global MX-5 Cup Steering column update to 2019 (tilt and telescoping) specifications

#### This TSB describes:

Optional changes to the GMX-5 cup car steering column with the addition of the telescoping feature to assist with driver comfort.

1. Part number ND6N-32-100 (2019+ Model year tilt & telescoping steering column) may now be substituted for NA1J-32-100 (2016 – 2018 tilt steering column). When updating to the 2019 style column, you will also need three additional parts. Mazda part numbers:
  - a. 0000-08-D230 Updated MXL2 mount
  - b. 0000-08-D234 Modified start/stop wiring harness
  - c. 0000-08-D235 Fire bottle line



#### Installation:

Follow all of the Mazda factory service manual procedures

If you have any questions about this Technical Bulletin, please contact Long Road Racing at: [Info@LongRoadRacing.com](mailto:Info@LongRoadRacing.com) or 980-223-8547