



Long Road Racing

2668 Peachtree Road ▪ Statesville, NC 28625 ▪ Phone: 980-223-8547

Since 2001

LongRoadRacing.com

Global MX-5 Cup Car Technical Service Bulletin #7-20-16


Trunk washer upgrade

Purpose for this TSB:

1. Replace the flat washers that support the transmission and differential oil coolers

Installation:

1. Follow all safety standards and wear the appropriate safety gear
2. Ensure that the kill switch is OFF, and the car has cooled down completely
3. An assistant makes this job much easier! Locate, remove the six small machine screws and discard the small washer (red arrow) that support the differential and transmission coolers and the used Nylock nut.
4. Please remove and replace one screw and new washer (green arrow) and new Nylock nut at a time so that the cooler assembly remains supported and all six of the holes align.



If you have any questions about this Technical Bulletin, please contact Glenn Long at:

GLENN@LongRoadRacing.COM or 919-614-4797