



## Long Road Racing

2668 Peachtree Road, Statesville, NC 28625

(980) 223-8547 LongRoadRacing.com

### Global MX-5 Cup Car Technical Service Bulletin #05-23-2018A


#### Optional: 2016 & 2017 Global MX-5 Update: Headlight leveling sensor

**This TSB describes:**

1. The headlight leveling sensor and sensor harness may be deleted.

**Installation:**

1. On 2016 and 2017 chassis' is now permitted to remove the headlight leveling sensor (N243-51-22ZA or B) and harness (N243-67-SH0A) from the left rear lower control arm.



(C) 2013 MAZDA Motor Corporation

If you have any questions about this Technical Bulletin, please contact Long Road Racing at:

[Glenn@LongRoadRacing.com](mailto:Glenn@LongRoadRacing.com) or 980-223-8547